

## MT. BALDY

### Impact Protection ([Click Here](#) for Scoring Methodology)

Category ( <a href="#">Click Here</a> for In-depth Information)	Score									
	1	2	3	4	5	6	7	8	9	10
LIFT-RELATED STRUCTURES (All Lift Towers, Posts, Buildings and Low Chairs in Terminal Area)										
SNOWMAKING HYDRANTS AND GUNS AND OTHER POSTS AND POLES ON TRAILS										
EXPOSED SNOWMAKING AIR AND WATER SUPPLY PIPES										
PARKED VEHICLES ON TRAILS										
OUT BUILDINGS (Other than at Lift Terminals)										
BEGINNER TRAIL TREES (Isolated Trees on Beginner Terrain)										
SIDE-SLOPE TRAILS (Trails that Tilt to One Side With Obstacles Below)										
CHAIRLIFT RESTRAINT BARS										

### Trail Design and Maintenance ([Click Here](#) Scoring Methodology)

Category ( <a href="#">Click Here</a> for In-depth Information)	Score									
	1	2	3	4	5	6	7	8	9	10
BLIND INTERSECTIONS										
DIVERGENT ABILITY INTERSECTIONS (Advanced Into Beginner)										
TRAIL CONGESTION AREAS										
EGRESS INTO BEGINNER LEARNING AREAS	N/A									
EGRESS INTO SLOW AND FAMILY AREAS	N/A									
SURFACE HAZARDS (Sinkholes, Drainages, Road Cuts, Etc.)										
EXTREME TERRAIN HAZARDS (Cliffs, Avalanche Terrain, Etc.)										
MOVING HAZARDS (Vehicles – Except Emergency Vehicles – and Low Hanging Chairs)										
INADVERTENT ENTRY INTO EXEMPT TERRAIN	N/A									

[Click Here](#) for Information on this Resort's Boundaries

[Click Here](#) for Information on this Resort's Terrain Parks

## MT. BALDY

# Impact Protection

IMPACT PROTECTION	SCORE	COMMENTS FROM FIELD OBSERVERS
<b>LIFT-RELATED STRUCTURES</b> (All Lift Towers. Posts, Buildings and Low Chairs in Terminal Area)	<b>0</b>	Towers: No impact mitigation devices used (some had rope and bamboo - to warn?) (0 pts). Post and poles: No mitigation (0 pts). Buildings: No mitigation (0 pts). Low Chairs: All had rope and bamboo (1 pt). Total: 1 pt ÷ 4 categories = 0.25 pts rounded to zero.
<b>SNOWMAKING HYDRANTS AND GUNS AND OTHER POSTS AND POLES ON TRAILS</b>	<b>0.5</b>	Hydrants/guns: A few were partially bermed; most had no mitigation (1 pt). Other posts/poles: No mitigation (0 pts). Total: 1 pt ÷ 2 categories = 0.5 pts.
<b>EXPOSED SNOWMAKING AIR AND WATER SUPPLY PIPES</b>	<b>0</b>	One observed; no mitigation (0 pts).
<b>PARKED VEHICLES ON TRAILS</b>	<b>0</b>	Several (some apparently derelict) vehicles observed had no mitigation (0 pts).
<b>OUT BUILDINGS</b> (Other than at Lift Terminals)	<b>0</b>	All had no mitigation (0 pts).
<b>BEGINNER TRAIL TREES</b> (Isolated Trees on Beginner Terrain)	<b>0</b>	A few observed; no mitigation (0 pts).
<b>SIDE-SLOPE TRAILS</b> (Trails that Tilt to One Side With Obstacles Below)	<b>0</b>	A few observed; no mitigation (0 pts).
<b>CHAIRLIFT RESTRAINT BARS</b>	<b>7.5</b>	Three out of four chairlifts had restraint bars (7.5 pts).

## MT. BALDY

# Trail Design and Maintenance

IMPACT PROTECTION	SCORE	COMMENTS FROM FIELD OBSERVERS
<b>BLIND INTERSECTIONS</b>	<b>10</b>	None observed (10 pts).
<b>DIVERGENT ABILITY INTERSECTIONS</b> (Advanced Into Beginner)	<b>2</b>	One had signs; remainder had no mitigation (2 pts).
<b>TRAIL CONGESTION AREAS</b>	<b>2</b>	One had signs; remainder had no mitigation (2 pts).
<b>EGRESS INTO BEGINNER LEARNING AREAS</b>	<b>N/A</b>	No beginner learning areas designated on trail map (N/A).
<b>EGRESS INTO SLOW AND FAMILY AREAS</b>	<b>N/A</b>	None designated on trail map (N/A).
<b>SURFACE HAZARDS</b> (Sinkholes, Drainages, Road Cuts, Etc.)	<b>0</b>	Many observed; all had no mitigation (0 pts).
<b>EXTREME TERRAIN HAZARDS</b> (Cliffs, Avalanche Terrain, Etc.)	<b>0</b>	Many observed; all had no mitigation (0 pts).
<b>MOVING HAZARDS</b> (Vehicles – Except Emergency Vehicles – and Low Hanging Chairs)	<b>0</b>	Four snowmobiles observed; all had no mitigation (0 pts).
<b>INADVERTENT ENTRY INTO EXEMPT TERRAIN</b>	<b>N/A</b>	None designated on trail map (N/A).

## MT. BALDY – CHAIR 1 AND 3 AREAS

# Resort Boundaries

N = North    E = East    W = West    S = South

	OPEN				CLOSED				GATED			
	N	E	W	S	N	E	W	S	N	E	W	S
<b>BOUNDARY AND/OR CLOSED SIGNS</b>		*	**									
<b>BARRIERS</b> Rope and Bamboo/Fences		*										
<b>SIGNS WARNING OF SIDE-COUNTRY DANGERS</b>												
<b>STAFF POSTED AT EXIT GATE</b>												
<b>NOT DESIGNATED</b>												

\* East boundary: Significant gaps observed in rope and sign line.

\*\* Lower West boundary off of chair 1 not observed.

**Note:**

South boundary is parking lot.

## MT. BALDY – CHAIR 4 AREA

# Resort Boundaries

N = North    E = East    W = West    S = South

	OPEN				CLOSED				GATED			
	N	E	W	S	N	E	W	S	N	E	W	S
<b>BOUNDARY AND/OR CLOSED SIGNS</b>	*	*	**									
<b>BARRIERS</b> Rope and Bamboo/Fences	X											
<b>SIGNS WARNING OF SIDE-COUNTRY DANGERS</b>												
<b>STAFF POSTED AT EXIT GATE</b>												
<b>NOT DESIGNATED</b>												

- \* North and East boundaries: Half of signs were severely faded or blank.
- \*\* West boundary: Only one sign observed; no other indicators of boundary line.

**Note:**  
South boundary is parking lot.

## MT. BALDY

# Terrain Parks

IMPACT PROTECTION	NONE	SOME	HALF	MOST	ALL	UNKNOWN
<b>DEFINED BOUNDARIES</b>	*					
<b>DIFFICULTY RATING POSTED</b>	X					
<b>SPOTTER REQUIRED</b>	X					
<b>SPEED CONTROLS FOR JUMPS</b>	X					
<b>HALF PIPE ROPE OFF</b>						**
<b>FEATURES ENGINEERED</b>						X
<b>TAKEOFF SPOTS FLAGGED</b>	X					

\* Chair 4 area terrain features: Entrance sign face down on snow, boundary ribbon down. Terrain feature at notch: Incomplete and ineffective ropes and signs.

\*\* No half pipe observed.