



**HEAVENLY VALLEY**  
**(California Side Only)**  
**Impact Protection**

IMPACT PROTECTION	SCORE	COMMENTS FROM FIELD OBSERVERS
<b>LIFT-RELATED STRUCTURES</b> (All Lift Towers, Posts, Buildings and Low Chairs in Terminal Area)	4.13	Towers: Tram towers had rope and bamboo; all other lift towers had open cell foam pads (2.5 pts.). Post and poles: Some had open cell foam pads; some had rope and bamboo (2 pts.). Buildings: None observed (10 pts.). Low chairs: Low hanging chairs were all roped (1 pt.); plus 1 pt. for plastic poles in lift maze. Total: 16.5 pts. ÷ 4 categories = 4.13 pts.
<b>SNOWMAKING HYDRANTS AND GUNS AND OTHER POSTS AND POLES ON TRAILS</b>	1	Hydrants/guns: Some had hard cone covers; some had open cell foam pads; some had no mitigation (1 pt.). Other posts and poles: Most had open cell foam pads; some had no mitigation (1 pt.). Total: 2 pts. ÷ 2 categories = 1 pt.
<b>EXPOSED SNOWMAKING AIR AND WATER SUPPLY PIPES</b>	0	Open pipes observed on Gun Barrel, California Trail at Tamarack – no signs; no mitigation (0 pts.).
<b>PARKED VEHICLES ON TRAILS</b>	9	Most were parked out of collision paths, but still near trails (9 pts.).
<b>OUT BUILDINGS</b> (Other than at Lift Terminals)	6.25	One at race bottom; two at top of terrain park protected by bushy vegetation (8 pts.). One at snowmaking pump house on Lower Maggies with rope and bamboo (1 pt.) Total: 24 pts. + 1 pt. = 25 ÷ 4 = 6.25 pts.
<b>BEGINNER TRAIL TREES</b> (Isolated Trees on Beginner Terrain)	10	None observed (10 pts.).
<b>SIDE-SLOPE TRAILS</b> (Trails that Tilt to One Side with Obstacles Below)	0	One observed at Waterfall and Catrack (0 pts.).
<b>CHAIRLIFT RESTRAINT BARS</b>	10	All observed chairlifts had restraint bars (10 pts.).

**HEAVENLY VALLEY**  
**(California Side Only)**  
**Trail Design and Maintenance**

IMPACT PROTECTION	SCORE	COMMENTS FROM FIELD OBSERVERS
<b>BLIND INTERSECTIONS</b>	8	All blind intersections had breakaway ropes with signs. Some had pre-warning signs up slope (8 pts.).
<b>DIVERGENT ABILITY INTERSECTION</b> (Advanced into Beginner)	3	Signs only at West Bowl and none at Fall Line/Waterfall (3 pts.).
<b>TRAIL CONGESTION AREAS</b>	10	None observed (10 pts.).
<b>EGRESS INTO BEGINNER LEARNING AREAS</b>	8	Designated learning areas were mostly geographically isolated and partially fenced or signed (8 pts.).
<b>EGRESS INTO SLOW AND FAMILY AREAS</b>	5	Signs only except at Waterfall, Fall Line and Powder Line (5 pts.).
<b>SURFACE HAZARDS</b> (Sinkholes, Drainages, Road Cuts, etc.)	3	Most rock and log hazards were unmarked. One road cut on Upper Mombo was wanded with caution signs (3 pts.).
<b>EXTREME TERRAIN HAZARDS</b> (Cliffs, Avalanche Terrain, etc.)	8	Pond and creek on Maggies was roped and signed (8 pts.).
<b>MOVING HAZARDS</b> (Vehicles - Except Emergency Vehicles and Low Hanging Chairs)	8.5	Low chairs all roped; no moving snowmobiles (8.5 pts.).
<b>INADVERTENT ENTRY INTO EXEMPT TERRAIN</b>	8	Areas next to groomed trails are obvious or roped and signed; Powder Bowl Woods is gated and geo-isolated (8 pts.).

# HEAVENLY VALLEY (California Side Only) Resort Boundaries

N = North    E = East    W = West    S = South

	OPEN				CLOSED				GATED			
	N	E	W	S	N	E	W	S	N	E	W	S
<b>BOUNDARY AND/OR CLOSED SIGNS</b>		1	1	1			1,2					
<b>BARRIERS ROPE AND BAMBOO/FENCES</b>			1	1			1,2					
<b>SIGNS WARNING OF SIDE COUNTRY DANGERS</b>												
<b>STAFF POSTED AT EXIT GATE</b>												
<b>NOT DESIGNATED</b>												

1 - Southeast strategic signs. Southwest ropes and signs. West signs only. West boundary (top half) had signs and ropes saying "access through gates" but no gates found. West boundary (lower half) had some closed signs and then ropes only to bottom of race slope.

2 - Powder Bowl Woods west boundary signed and roped. Roundabout signed and roped. Tamarack boundary not observed (north boundary).

**HEAVENLY VALLEY**  
**(California Side Only)**  
**Terrain Parks**

	NONE	SOME	HALF	MOST	ALL	UNKNOWN
DEFINED BOUNDARIES					X	
DIFFICULTY RATING POSTED					X	
SPOTTER REQUIRED	X					
SPEED CONTROLS FOR JUMPS	X					
HALFPIPE ROPED OFF			X**			
FEATURES ENGINEERED						X
TAKEOFF SPOTS FLAGGED					*	
<p>No halfpipe observed. **Two ¼ pipes observed; one deck fenced – one has no marking.  *Jump takeoffs are flagged; hits are not.</p>						