

HOMWOOD

Impact Protection [\(Click Here for Scoring Methodology\)](#)

Category	Score									
	1	2	3	4	5	6	7	8	9	10
LIFT-RELATED STRUCTURES (All Lift Towers, Posts, Buildings and Low Chairs in Terminal Area)										
SNOWMAKING HYDRANTS AND GUNS AND OTHER POSTS AND POLES ON TRAILS										
EXPOSED SNOWMAKING AIR AND WATER SUPPLY PIPES										
PARKED VEHICLES ON TRAILS										
OUT BUILDINGS (Other than at Lift Terminals)										
BEGINNER TRAIL TREES (Isolated Trees on Beginner Terrain)										
SIDE-SLOPE TRAILS (Trails that Tilt to One Side with Obstacles Below)										
CHAIRLIFT RESTRAINT BARS										

Trail Design and Maintenance [\(Click Here Scoring Methodology\)](#)

Category	Score									
	1	2	3	4	5	6	7	8	9	10
BLIND INTERSECTIONS										
DIVERGENT ABILITY INTERSECTION (Advanced into Beginner)										
TRAIL CONGESTION AREAS										
EGRESS INTO BEGINNER LEARNING AREAS										
EGRESS INTO SLOW AND FAMILY AREAS										
SURFACE HAZARDS (Sinkholes, Drainages, Road Cuts, etc.)										
EXTREME TERRAIN HAZARDS (Cliffs, Avalanche Terrain, etc.)										
MOVING HAZARDS (Vehicles - Except Emergency Vehicles and Low Hanging Chairs)										
INADVERTENT ENTRY INTO EXEMPT TERRAIN										

HOMWOOD

Impact Protection

IMPACT PROTECTION	SCORE	COMMENTS FROM FIELD OBSERVERS
LIFT-RELATED STRUCTURES (All Lift Towers, Posts, Buildings and Low Chairs in Terminal Area)	1.5	Towers: All had open cell foam pads (3 pts.). Post and poles: All had rope and bamboo (1 pt.). Buildings: All had rope and bamboo (1 pt.). Low chairs: All had rope and bamboo (1 pt.). Total: 6 pts. ÷ 4 categories = 1.5 pts.
SNOWMAKING HYDRANTS AND GUNS AND OTHER POSTS AND POLES ON TRAILS	4	All had open cell foam pads (3 pts.) and rope and bamboo (plus 1 pt.). Total: 4 pts.
EXPOSED SNOWMAKING AIR AND WATER SUPPLY PIPES	10	None observed (10 pts.).
PARKED VEHICLES ON TRAILS	8	All parked at inaccessible locations or behind ropes (8 pts.).
OUT BUILDINGS (Other than at Lift Terminals)	1	All had rope and bamboo (1 pt.)
BEGINNER TRAIL TREES (Isolated Trees on Beginner Terrain)	10	None observed (10 pts.).
SIDE-SLOPE TRAILS (Trails that Tilt to One Side with Obstacles Below)	0	Pot o' Gold and Sunnyside – no mitigation (0 pts.).
CHAIRLIFT RESTRAINT BARS	5	Two out of four chairlifts had restraint bars (5 pts.).

HOMEWOOD

Trail Design and Maintenance

IMPACT PROTECTION	SCORE	COMMENTS FROM FIELD OBSERVERS
BLIND INTERSECTIONS	0	One observed; no mitigation (0 pts.).
DIVERGENT ABILITY INTERSECTION (Advanced into Beginner)	0	Drainpipe had no mitigation (0 pts.).
TRAIL CONGESTION AREAS	10	None observed (10 pts.).
EGRESS INTO BEGINNER LEARNING AREAS	2.5	Cedar Ridge to Children's Learning Center – no mitigation (0 pts.). Some ropes and fences at Happy Park (5 pts.). Total: 5 pts. ÷ 2 categories = 2.5 pts.
EGRESS INTO SLOW AND FAMILY AREAS	0	No points of entry had signs (0 pts.).
SURFACE HAZARDS (Sinkholes, Drainages, Road Cuts, etc.)	8	One observed with signs and markers (8 pts.).
EXTREME TERRAIN HAZARDS (Cliffs, Avalanche Terrain, etc.)	6	Quail Face cliffs were all signed (6 pts.).
MOVING HAZARDS (Vehicles - Except Emergency Vehicles and Low Hanging Chairs)	4.5	Three snowmobiles observed with flags only (1 pt.). Low chairs were roped and signed (8 pts.). Total: 9 pts. ÷ 2 categories: 4.5 pts.
INADVERTENT ENTRY INTO EXEMPT TERRAIN	6	All points of entry had signs only (6 pts.).

HOMewood

Terrain Parks

	NONE	SOME	HALF	MOST	ALL	UNKNOWN
DEFINED BOUNDARIES			X			
DIFFICULTY RATING POSTED			X			
SPOTTER REQUIRED	X					
SPEED CONTROLS FOR JUMPS	X					
HALFPIPE ROPED OFF						X
FEATURES ENGINEERED						X
TAKEOFF SPOTS FLAGGED						X
No halfpipe observed.						