

MT. ROSE

Impact Protection ([Click Here](#) for Scoring Methodology)

Category	SCORE									
	1	2	3	4	5	6	7	8	9	10
LIFT RELATED STRUCTURES (All Lift Towers, Posts, Buildings and Low Chairs in Terminal Area.)	■	■								
SNOWMAKING HYDRANTS & GUNS AND OTHER POSTS & POLES ON TRAILS	■	■								
EXPOSED SNOWMAKING AIR AND WATER SUPPLY PIPES	■	■	■	■	■	■	■	■	■	■
PARKED VEHICLES ON TRAILS	■	■	■	■	■	■	■	■	■	■
OUT BUILDINGS (other than at lift terminals)	■									
BEGINNER TRAIL TREES (Isolated Trees on Beginner Terrain)	■	■	■	■	■	■	■	■	■	■
SIDE-SLOPE TRAILS (Trails That Tilt to One Side with Obstracles Below)	■	■	■	■						
CHAIRLIFT RESTRAINT BARS	■	■	■	■	■	■	■			

Trail Design and Maintenance ([Click Here](#) Scoring Methodology)

Category	SCORE									
	1	2	3	4	5	6	7	8	9	10
BLIND INTERSECTIONS										
DIVERGENT ABILITY INTERSECTIONS (Advanced into Beginner)										
TRAIL CONGESTION AREAS										
EGRESS INTO BEGINNER LEARNING AREAS										
EGRESS INTO SLOW AND FAMILY AREAS										
SURFACE HAZARDS (Sinkholes, Drainages, Road Cuts, etc.)										
EXTREME TERRAIN HAZARDS (Cliffs, Avalanche Terrain, Etc.)										
MOVING HAZARDS (Vehicles - Except Emergency Vehicles and Low Hanging Chairs)										
INADVERTENT ENTRY INTO EXEMPT TERRAIN	N/A									

MT. ROSE

Impact Protection

IMPACT PROTECTION	SCORE	COMMENTS FROM FIELD OBSERVERS
LIFT-RELATED STRUCTURES (All Lift Towers, Posts, Buildings and Low Chairs in Terminal Area)	2	All lift towers padded with open cell foam (3 pts.); structures all were flagged with rope (1 pt.); outbuildings and posts – some had strategic catch fencing (2 pts.); low chairs all roped off. (3 + 1 + 2 ÷ 3 = 2 pts.)
SNOWMAKING HYDRANTS AND GUNS AND OTHER POSTS AND POLES ON TRAILS	2	Most snowmaking and posts had open cell foam (some pads were buried and some missing) (2 pts.).
EXPOSED SNOWMAKING AIR AND WATER SUPPLY PIPES	10	All had bamboo and flagged ropes (10 pts.).
PARKED VEHICLES ON TRAILS	10	Two snowmobiles parked at bottom of "NW" behind trees – none on trails (10 pts.).
OUT BUILDINGS (Other than at Lift Terminals)	1	All had bamboo and flagged ropes (1 pt.).
BEGINNER TRAIL TREES (Isolated Trees on Beginner Terrain)	10	None observed (10 pts.).
SIDE-SLOPE TRAILS (Trails that Tilt to One Side with Obstacles Below)	4	Two observed – lower "Lakeview" and "Sunset" had catch fence (8 pts.); "Washoe Zephyr" to "Log Flume" had none (0 pts.).
CHAIRLIFT RESTRAINT BARS	6.7	Four out of six (6.7 pts.).
		*No designated beginners' area on map; however, we are saying "Flying Jenny" and "Little Mule" were used as specific learning areas and geo-isolated.

MT. ROSE

Trail Design and Maintenance

Category	SCORE	COMMENTS FROM FIELD OBSERVERS
BLIND INTERSECTIONS	6	Most (?) signed and roped (6 pts.).
DIVERGENT ABILITY INTERSECTIONS (Advanced into Beginner)	9	One at "Sunset" and lower "Lakeview" marked with barrier fencing with flagging (9 pts.).
TRAIL CONGESTION AREAS	10	None observed (10 pts.).
EGRESS INTO BEGINNER LEARNING AREAS	10	Geo-isolated area with rope at top for "Flying Jenny and "Show Off" (10 pts.).
EGRESS INTO SLOW AND FAMILY AREAS	7	Gated "Wild Horse Park" ("Bronco" and "Mustang" are Kids Only with Adult); none others (6 pts. + 1 pt. for geo-isolated = 7 pts.).
SURFACE HAZARDS (Sinkholes, Drainages, Road Cuts, Etc.)	5	One observed on "Galena" with x-bamboo; road cuts not mitigated – "Kit Carson" and "High Traverse" (5 pts.).
EXTREME TERRAIN HAZARDS (Cliffs, Avalanche Terrain, Etc.)	9	"The Chutes" were gated, signed and roped (9 pts.).
MOVING HAZARDS (Vehicles – Except Emergency Vehicles and Low Hanging Chairs)	2	All low chairs were roped and one snowmobile observed with light and flag in beginner area (2 pts.).
INADVERTENT ENTRY INTO EXEMPT TERRAIN	N/A	None observed.

MT. ROSE Resort Boundaries

N = North E = East W = West S = South

	OPEN				CLOSED				GATED			
	N	E	W	S	N	E	W	S	N	E	W	S
BOUNDARY AND/OR CLOSED SIGNS		1		1			X					2
BARRIERS ROPE & BAMBOO/FENCES		1		1			X					
SIGNS WARNING OF SIDE COUNTRY DANGERS		1		1								2
STAFF POSTED AT EXIT GATE												
NOT DESIGNATED	3	X										
1 – Slide Bowl side 2 – Mt. Rose side (has road for East boundary). 3 – North boundary is Mt. Rose Highway and Slide Bowl access Road. *West closed from “Mustang” down. *Ropes and signs stop at steep, upslope natural boundary top of South border.												

MT. ROSE Terrain Parks

	NONE	SOME	HALF	MOST	ALL	UNKNOWN
DEFINED BOUNDARIES	1					
DIFFICULTY RATING POSTED					2	
SPOTTER REQUIRED	X					
SPEED CONTROLS FOR JUMPS	X					
HALFPIPE ROPED OFF						
FEATURES ENGINEERED						X
TAKEOFF SPOTS FLAGGED					X	
<p>1 - West side mostly roped; East side open to trees. 2 - Entry marked, but confusing - no individual ratings for features. *No half-pipe observed.</p>						