

## DODGE RIDGE

### Impact Protection [\(Click Here for Scoring Methodology\)](#)

Category	Score									
	1	2	3	4	5	6	7	8	9	10
<b>LIFT-RELATED STRUCTURES</b> (All Lift Towers, Posts, Buildings and Low Chairs in Terminal Area)										
<b>SNOWMAKING HYDRANTS AND GUNS AND OTHER POSTS AND POLES ON TRAILS</b>										
<b>EXPOSED SNOWMAKING AIR AND WATER SUPPLY PIPES</b>										
<b>PARKED VEHICLES ON TRAILS</b>										
<b>OUT BUILDINGS</b> (Other than at Lift Terminals)										
<b>BEGINNER TRAIL TREES</b> (Isolated Trees on Beginner Terrain)										
<b>SIDE-SLOPE TRAILS</b> (Trails that Tilt to One Side with Obstacles Below)										
<b>CHAIRLIFT RESTRAINT BARS</b>										

### Trail Design and Maintenance [\(Click Here Scoring Methodology\)](#)

Category	Score									
	1	2	3	4	5	6	7	8	9	10
<b>BLIND INTERSECTIONS</b>										
<b>DIVERGENT ABILITY INTERSECTION</b> (Advanced into Beginner)										
<b>TRAIL CONGESTION AREAS</b>										
<b>EGRESS INTO BEGINNER LEARNING AREAS</b>										
<b>EGRESS INTO SLOW AND FAMILY AREAS</b>										
<b>SURFACE HAZARDS</b> (Sinkholes, Drainages, Road Cuts, etc.)										
<b>EXTREME TERRAIN HAZARDS</b> (Cliffs, Avalanche Terrain, etc.)										
<b>MOVING HAZARDS</b> (Vehicles - Except Emergency Vehicles and Low Hanging Chairs)										
<b>INADVERTENT ENTRY INTO EXEMPT TERRAIN</b>	N/A									

## DODGE RIDGE

# Impact Protection

IMPACT PROTECTION	SCORE	COMMENTS FROM FIELD OBSERVERS
<b>LIFT-RELATED STRUCTURES</b> (All Lift Towers, Posts, Buildings and Low Chairs in Terminal Area)	2.25	Towers: All had open cell foam pads (3 pts.). Posts and poles: All had open cell foam pads (3 pts.). Buildings: All had rope and bamboo (1 pt.). Low chairs: All had rope and bamboo except chair 6 which had closed signs (1 pt.). Lift mazes used plastic poles (+1 pt.) Total: 9 pts. ÷ 4 categories = 2.25 pts.
<b>SNOWMAKING HYDRANTS AND GUNS AND OTHER POSTS AND POLES ON TRAILS</b>	6.5	Hydrants/guns: None observed (10 pts.). Other posts/poles: All had open cell foam pads (3 pts.). Total: 13 pts. ÷ 2 categories = 6.5 pts.
<b>EXPOSED SNOWMAKING AIR AND WATER SUPPLY PIPES</b>	10	None observed (10 pts.).
<b>PARKED VEHICLES ON TRAILS</b>	10	None observed (10 pts.).
<b>OUT BUILDINGS</b> (Other than at Lift Terminals)	1	All but one had no mitigation (1 pt.).
<b>BEGINNER TRAIL TREES</b> (Isolated Trees on Beginner Terrain)	10	None observed (10 pts.).
<b>SIDE-SLOPE TRAILS</b> (Trails that Tilt to One Side with Obstacles Below)	0	Two observed (Clementine and Gold Nugget; no mitigation (0 pt.).
<b>CHAIRLIFT RESTRAINT BARS</b>	0	No chairlifts had restraint bars (0 pts.).

## DODGE RIDGE

# Trail Design and Maintenance

IMPACT PROTECTION	SCORE	COMMENTS FROM FIELD OBSERVERS
<b>BLIND INTERSECTIONS</b>	8	All had signs and markers (8 pts.).
<b>DIVERGENT ABILITY INTERSECTION</b> (Advanced into Beginner)	10	None observed (Corkscrew, Nose, etc. closed at time of observations) (10 pts.).
<b>TRAIL CONGESTION AREAS</b>	10	None observed (10 pts.).
<b>EGRESS INTO BEGINNER LEARNING AREAS</b>	9	Designated learning area was geo-isolated; partially signed and partially roped (9 pts.).
<b>EGRESS INTO SLOW AND FAMILY AREAS</b>	9	One point of entry had a fence at top of chair 6 (9 pts.).
<b>SURFACE HAZARDS</b> (Sinkholes, Drainages, Road Cuts, etc.)	7	All had markers; some had signs, too (7 pts.).
<b>EXTREME TERRAIN HAZARDS</b> (Cliffs, Avalanche Terrain, etc.)	5	Most had signs; some had no mitigation (5 pts.).
<b>MOVING HAZARDS</b> (Vehicles - Except Emergency Vehicles and Low Hanging Chairs)	7	One snowmobile observed with flag in middle of open trail. Elsewhere isolated lanes for snowmobiles (7 pt.).
<b>INADVERTENT ENTRY INTO EXEMPT TERRAIN</b>	N/A	None designated on trail map (N/A).

## DODGE RIDGE Resort Boundaries

N = North    E = East    W = West    S = South

	OPEN				CLOSED				GATED			
	N	E	W	S	N	E	W	S	N	E	W	S
<b>BOUNDARY AND/OR CLOSED SIGNS</b>			**		X	X*	*	X				
<b>BARRIERS</b>												
<b>ROPE AND BAMBOO/FENCES</b>												
<b>SIGNS WARNING OF SIDE COUNTRY DANGERS</b>												
<b>STAFF POSTED AT EXIT GATE</b>												
<b>NOT DESIGNATED</b>												
<p>*Interior boundary between Quick Silver and Graceland; out-of-bounds area signed.</p> <p>**Upper west boundary closed to access.</p>												

## DODGE RIDGE

# Terrain Parks

	NONE	SOME	HALF	MOST	ALL	UNKNOWN
DEFINED BOUNDARIES					Ropes X	
DIFFICULTY RATING POSTED					Sign M/L/X	
SPOTTER REQUIRED	X					
SPEED CONTROLS FOR JUMPS	X					
HALFPIPE ROPED OFF						
FEATURES ENGINEERED						X
TAKEOFF SPOTS FLAGGED				X		
No halfpipe observed.						