

GRANLIBAKKEN

Impact Protection [\(Click Here for Scoring Methodology\)](#)

Category	Score									
	1	2	3	4	5	6	7	8	9	10
LIFT-RELATED STRUCTURES (All Lift Towers, Posts, Buildings and Low Chairs in Terminal Area)										
SNOWMAKING HYDRANTS AND GUNS AND OTHER POSTS AND POLES ON TRAILS										
EXPOSED SNOWMAKING AIR AND WATER SUPPLY PIPES										
PARKED VEHICLES ON TRAILS										
OUT BUILDINGS (Other than at Lift Terminals)										
BEGINNER TRAIL TREES (Isolated Trees on Beginner Terrain)										
SIDE-SLOPE TRAILS (Trails that Tilt to One Side with Obstacles Below)										
CHAIRLIFT RESTRAINT BARS	N/A									

Trail Design and Maintenance [\(Click Here Scoring Methodology\)](#)

Category	Score									
	1	2	3	4	5	6	7	8	9	10
BLIND INTERSECTIONS										
DIVERGENT ABILITY INTERSECTION (Advanced into Beginner)										
TRAIL CONGESTION AREAS										
EGRESS INTO BEGINNER LEARNING AREAS	N/A									
EGRESS INTO SLOW AND FAMILY AREAS	N/A									
SURFACE HAZARDS (Sinkholes, Drainages, Road Cuts, etc.)										
EXTREME TERRAIN HAZARDS (Cliffs, Avalanche Terrain, etc.)	N/A									
MOVING HAZARDS (Vehicles - Except Emergency Vehicles and Low Hanging Chairs)										
INADVERTENT ENTRY INTO EXEMPT TERRAIN	N/A									

GRANLIBAKKEN

Impact Protection

IMPACT PROTECTION	SCORE	COMMENTS FROM FIELD OBSERVERS
LIFT-RELATED STRUCTURES (All Lift Towers, Posts, Buildings and Low Chairs in Terminal Area)	6.67	Towers: All had open cell foam pads (3 pts.). Post and poles: All had catch fences (8 pts.). Buildings: Two were nearly inaccessible and fenced (9 pts.). Low chairs: No chairlifts at resort (N/A). Total: 20 pts. ÷ 3 categories = 6.67 pts.
SNOWMAKING HYDRANTS AND GUNS AND OTHER POSTS AND POLES ON TRAILS	6.5	Hydrants/guns: None observed (10 pts). Other posts and poles: All had open cell foam pads (3 pts.). Total: 13 pts. ÷ 2 categories = 6.5 pts.
EXPOSED SNOWMAKING AIR AND WATER SUPPLY PIPES	10	None observed (10 pts.).
PARKED VEHICLES ON TRAILS	10	Groomer and snowmobiles were parked off area (10 pts.).
OUT BUILDINGS (Other than at Lift Terminals)	10	None observed. Lodge at base is uphill from slope bottom (10 pts.).
BEGINNER TRAIL TREES (Isolated Trees on Beginner Terrain)	10	None observed (10 pts.).
CHAIRLIFT RESTRAINT BARS	N/A	No chairlifts at resort (N/A).

GRANLIBAKKEN

Trail Design and Maintenance

IMPACT PROTECTION	SCORE	COMMENTS FROM FIELD OBSERVERS
BLIND INTERSECTIONS	10	None observed (10 pts.).
DIVERGENT ABILITY INTERSECTION (Advanced into Beginner)	10	None observed (10 pts.).
TRAIL CONGESTION AREAS	10	None observed (10 pts.).
EGRESS INTO BEGINNER LEARNING AREAS	N/A	No beginner learning area designated (N/A).
EGRESS INTO SLOW AND FAMILY AREAS	10	All terrain appears to be slow and family area (10 pts.).
SURFACE HAZARDS (Sinkholes, Drainages, Road Cuts, etc.)	10	One observed with a fence (10 pts.).
EXTREME TERRAIN HAZARDS (Cliffs, Avalanche Terrain, etc.)	N/A	None observed (N/A).
MOVING HAZARDS (Vehicles - Except Emergency Vehicles and Low Hanging Chairs)	0	No mitigation of surface lift up-track (0 pt.).
INADVERTENT ENTRY INTO EXEMPT TERRAIN	N/A	None designated on trail map (N/A).

GRANLIBAKKEN

Resort Boundaries

N = North E = East W = West S = South

	OPEN				CLOSED				GATED			
	N	E	W	S	N	E	W	S	N	E	W	S
BOUNDARY AND/OR CLOSED SIGNS												
BARRIERS												
ROPE AND BAMBOO/FENCES												
SIGNS WARNING OF SIDE COUNTRY DANGERS												
STAFF POSTED AT EXIT GATE												
NOT DESIGNATED		X	X	X								
North boundary is base of resort. No other designated boundaries.												

GRANLIBAKKEN

Terrain Parks

	NONE	SOME	HALF	MOST	ALL	UNKNOWN
DEFINED BOUNDARIES						
DIFFICULTY RATING POSTED						
SPOTTER REQUIRED						
SPEED CONTROLS FOR JUMPS						
HALFPIPE ROPED OFF						
FEATURES ENGINEERED						
TAKEOFF SPOTS FLAGGED						
No terrain parks at resort.						